

CROSSCO[®] TECHNICAL DATA

UHS – HIGH GLOSS FLOOR FINISH

FW2500 CODE: CK033

DESCRIPTION: CROSSCO – FW2500 is a fast dry, ultra high solids, durable floor finish with exceptional buffability. Tests on high traffic floor produce wear levels dramatically superior to conventional floor polishes on the market today. This product requires minimum maintenance, resists scuff marks thus reducing labor costs.

- RECOMMENDED CROSSCO FW2500 is the premium *Low Maintenance* floor finish that USES: provides high gloss and durability required for high traffic areas. Excellent for use on Vinyl, Vinyl Composition, Asphalt, Rubber, Concrete, Flagstone, Brick, Terrazzo, Sealed Wood floors. Designed for low maintenance floor care programs.
- ADVANTAGES: •Super High gloss finish •Could be used without sealer •Detergent resistant

For high traffic areasSelf levelingEasy to apply

PRODUCT CHARACTERISTICS

Solids 25.0 ± 0.5%	Dry/Recoat time40 min
ColorMilky White	DetergencyExcellent
OdorMild	Waterspot ResistanceExcellent
рН8.0 – 9.0	VOC0.35 lbs/gal
ViscosityWater thin	Coverage2500-3000 s.f./gal
Gloss90+ specular	Storage/Stability2 years
LevelingExcellent	Weight per Gallon9.15 lbs./gal.
BuffabiliyuSpray Buff or Restorer	Freeze / Thaw Stability Keep from freezing





FW2500

UHS – HIGH GLOSS FLOOR FINISH

GENERAL PRODUCT INFORMATION		
FOR USE	DIRECTIONS Cont.	
 Vinyl Tile Asphalt Tile Rubber Tile Flagstone Ceramic Tile Vinyl Asbestos Linoleum Concrete Terrazzo 	If floor is in good condition and stripping is not necessary, sweep up excess dirt and dust and then clean with a good quality cleaner to remove dirt and oils. Follow with a thorough rinsing and allow to dry completely.	
DIRECTIONS	<i>MAINTENANCE:</i> The floor may be maintained using a quality floor cleaner and damp mopping regularly.	
<u>New Application:</u> -Strip all old finish from floor using CROSSCO WX1000 Stripper. Rinse well with cold water until	Spray buffing or mop-on restoring may also be done after sweeping up loose dirt and dust. Follow directions for each product accordingly.	
no residue remains, and allow floor to dry thoroughly.	SCRUBBING & RECOATING	
 Once floor is stripped and dust free, apply a coat of <i>CROSSCO DP2000 Floor Sealer</i> to seal porous condition created by the stripper. Apply 3-4 medium, even coats of CROSSCO FW2500. Allow 20-30 minutes of drying time between each coat, depending on environmental conditions. Do not apply more than 4 coats within 24 hours. Excess coats will delay drying time between coats and may result in increased 	 Scrub traffic areas or the entire floor as required using ready-to-use surface preparation pads on an autoscrubber or rotary machine. Rinse floor with water until residue is removed and dust mop. Recoat the scrubbed area with 1-3 coats of the desired CROSSCO UHS floor finish, allowing 20-30 minutes between coats, depending on environmental conditions. 	
stickiness and dirt retention.	AVAILABLILITY	
-Floor may be opened to traffic 1 hour after final coat is applied.	CK033-1 55 GAL CK033-2 5 GAL CK033-4 4/1 GAL	
- Allow finish to cure 48-72 hours after application before burnishing	CK033-5 12/ 32oz Bottle	





GENERAL PRODUCT INFORMATION SAFETY INFORMATION LIMITATIONS Minimum application temperature is 50° F. Avoid contact with eyes, skin and clothing. Wear Full protective eyewear, gloves and footwear when hardness of the finish is achieved in 5-7 days. This handling. Avoid breathing of vapors. Keep out of product is ready-to-use...Do not dilute this product. Do not pour unused product back into the original reach of children. For use by trained personnel only. container. SUGGESTED STORAGE TEMPERATURE: Keep unauthorized personnel away when applying Store inside at 40-90°F. SPECIAL HANDLING AND to floor. Keep container closed during storage. For institutional and industrial use only. STORAGE: Handle in accordance with good industrial hygiene and safety practices. These practices include avoiding unnecessary exposure and removal of Refer to product Material Safety Data Sheet (MSDS) material from eyes, skin and clothing. Store in a prior to product use. cool, dry, ventilated area. Protect from freezing. Thoroughly rinse empty containers. For chemical emergency only, call Chemtrec 1-800-424-9300 WARRANTY Notice: The technical data contained herein are true Max Chemical, Inc. warrant only that this product is and accurate to the best of our knowledge. free of defects, since many factors which affects the Published instructions are subject to change results obtained from this product (such as weather, without prior notice. workmanship, equipment used and prior conditions of substrate) are beyond our control. We will replace at no charge any product proven to be defective within 90 days of purchase, provided it has been applied as manufacturer's specifications.

