

FW2000
CODE: CK034

DESCRIPTION: CROSSCO – FW2000 is a highly detergent resistant, scrubbable, acrylized floor finish that dries to an ultra-dry bright gloss and maintains its exceptional gloss for extended periods of time under moderate to heavy traffic conditions. This high performance formula resists black heel marks and scuffing, and with minimal maintenance, retains its unusually hard durable glossy film.

RECOMMENDED USES: CROSSCO – FW2000 Can be used on all resilient and non-resilient flooring as well as sealed wood, cork, concrete, terrazzo and "no wax" floors. Excellent for use on Vinyl, Vinyl Composition, Asphalt, Rubber, Concrete, Flagstone, Brick, Terrazzo, Sealed Wood floors.

ADVANTAGES:

- High gloss finish
- Scuff Resistance
- Detergent Resistant
- Dry Bright Finish
- Self leveling
- Easy to apply

PRODUCT CHARACTERISTICS

Solids.....	20.0 ± 0.5%	Dry/Recoat time.....	40 min
Color.....	Milky White	Detergency	Excellent
Odor.....	Mild	Waterspot Resistance.....	Excellent
pH	8.0 – 9.0	VOC.....	0.35 lbs/gal
Viscosity	Water thin	Coverage.....	2000-2500 s.f./gal
Gloss	90+ specular	Storage/Stability	2 years
Leveling	Excellent	Weight per Gallon	9.15 lbs./gal.
Buffabiliyu	Spray Buff or Restorer	Freeze / Thaw Stability ..	Keep from freezing

FW2000

GENERAL PRODUCT INFORMATION

FOR USE	DIRECTIONS Cont.								
<ul style="list-style-type: none"> - Vinyl Tile - Asphalt Tile - Rubber Tile - Flagstone - Ceramic Tile 	<p>If floor is in good condition and stripping is not necessary, sweep up excess dirt and dust and then clean with a good quality cleaner to remove dirt and oils. Follow with a thorough rinsing and allow to dry completely.</p>								
<p>DIRECTIONS</p>	<p><i>MAINTENANCE:</i> The floor may be maintained using a quality floor cleaner and damp mopping regularly. Spray buffing or mop-on restoring may also be done after sweeping up loose dirt and dust. Follow directions for each product accordingly.</p>								
<p><u><i>New Application:</i></u> -Strip all old finish from floor using <i>CROSSCO WX1000 Stripper</i>. Rinse well with cold water until no residue remains, and allow floor to dry thoroughly.</p>	<p>SCRUBBING & RECOATING</p>								
<p>-Once floor is stripped and dust free, apply a coat of <i>CROSSCO DP2000 Floor Sealer</i> to seal porous condition created by the stripper.</p> <p>-Apply 3-4 medium, even coats of <i>CROSSCO FW2000</i>. Allow 20-30 minutes of drying time between each coat, depending on environmental conditions. Do not apply more than 4 coats within 24 hours. Excess coats will delay drying time between coats and may result in increased stickiness and dirt retention.</p>	<ul style="list-style-type: none"> - Scrub traffic areas or the entire floor as required using ready-to-use surface preparation pads on an autoscrubber or rotary machine. - Rinse floor with water until residue is removed and dust mop. - Recoat the scrubbed area with 1-3 coats of the desired <i>CROSSCO UHS</i> floor finish, allowing 20-30 minutes between coats, depending on environmental conditions. 								
<p>-Floor may be opened to traffic 1 hour after final coat is applied.</p> <p>- Allow finish to cure 48-72 hours after application before burnishing</p>	<p>AVAILABILITY</p> <table border="0"> <tr> <td>CK034-1</td> <td>55 GAL</td> </tr> <tr> <td>CK034-2</td> <td>5 GAL</td> </tr> <tr> <td>CK034-4</td> <td>4/ 1 GAL</td> </tr> <tr> <td>CK034-5</td> <td>12/ 32oz Bottle</td> </tr> </table>	CK034-1	55 GAL	CK034-2	5 GAL	CK034-4	4/ 1 GAL	CK034-5	12/ 32oz Bottle
CK034-1	55 GAL								
CK034-2	5 GAL								
CK034-4	4/ 1 GAL								
CK034-5	12/ 32oz Bottle								

FW2000

GENERAL PRODUCT INFORMATION

LIMITATIONS

Minimum application temperature is 50° F. Full hardness of the finish is achieved in 5-7 days. This product is ready-to-use...Do not dilute this product. Do not pour unused product back into the original container. SUGGESTED STORAGE TEMPERATURE: Store inside at 40-90°F. SPECIAL HANDLING AND STORAGE: Handle in accordance with good industrial hygiene and safety practices. These practices include avoiding unnecessary exposure and removal of material from eyes, skin and clothing. Store in a cool, dry, ventilated area. Protect from freezing. Thoroughly rinse empty containers.

WARRANTY

Max Chemical, Inc. warrant only that this product is free of defects, since many factors which affects the results obtained from this product (such as weather, workmanship, equipment used and prior conditions of substrate) are beyond our control. We will replace at no charge any product proven to be defective within 90 days of purchase, provided it has been applied as manufacturer's specifications.

SAFETY INFORMATION

Avoid contact with eyes, skin and clothing. Wear protective eyewear, gloves and footwear when handling. Avoid breathing of vapors. Keep out of reach of children. For use by trained personnel only. Keep unauthorized personnel away when applying to floor. Keep container closed during storage. For institutional and industrial use only.

Refer to product Material Safety Data Sheet (MSDS) prior to product use.

For chemical emergency only, call Chemtrec 1- 800-424-9300

Notice: The technical data contained herein are true and accurate to the best of our knowledge. Published instructions are subject to change without prior notice.